

| Description | Wire Size | Stud/Tab Width | Crimp & Seal (A) | Solder & Seal (B) | Crimp, Solder & Seal (C) | NYAX Crimp & Seal (A) |
|--------------------------------|-----------|--------------------|------------------|-------------------|--------------------------|-----------------------|
| Spades | 16-14 Ga. | 6 Flanged | 40143 | | | 70143 |
| | | 8 | 40150 | | | 70150 |
| | | 8 Snap | 40151 | | | 70151 |
| | | 8 Block | 40152 | | | 70152 |
| | | 8 Flanged | 40153 | | | 70153 |
| | | 10 | 40160 | 60160 | 80160 | 70160 |
| | | 10 Snap | 40161 | | | 70161 |
| | | 10 Block | 40162 | | | 70162 |
| Spades | 12-10 Ga. | 6 | 40270 | | | 70270 |
| | | 6 Snap | 40271 | | | 70271 |
| | | 6 Block | 40272 | | | 70272 |
| | | 6 Flanged | 40273 | | | 70273 |
| | | 8 | 40280 | | | 70280 |
| | | 8 Snap | 40281 | | | 70281 |
| | | 8 Block | 40282 | | | 70282 |
| | | 8 Flanged | 40283 | | | 70283 |
| | | 10 | 40290 | 60290 | 80290 | 70290 |
| | | 10 Snap | 40291 | | | 70291 |
| | | 10 Block | 40292 | | | 70292 |
| | | 10 Flanged | 40293 | | | 70293 |
| | | 1/4 | 40234 | | | 70234 |
| | | 1/4 Snap | 40241 | | | 70241 |
| Hooks | 22-16 Ga. | 6 | 40067 | | | 70067 |
| | | 8 | 40077 | | | 70077 |
| | | 10 | 40087 | | | 70087 |
| Hooks | 16-14 Ga. | 6 | 40105 | | | 70105 |
| | | 8 | 40110 | | | 70110 |
| | | 10 | 40120 | | | 70120 |
| Hooks | 12-10 Ga. | 6 | 40128 | | | 70128 |
| | | 8 | 40129 | | | 70129 |
| | | 10 | 40130 | | | 70130 |
| Quick Connects | 22-18 Ga. | .110 Tab Female | 40191 | | | 70191 |
| | | .187 Tab Female | 40192 | | | 70192 |
| | | .187 Tab Male | 40197 | | | 70197 |
| | | .250 Tab Female | 40176 | 60176 | 80176 | 70176 |
| | | .250 Tab Male | 40177 | 60177 | 80177 | 70177 |
| | | .250 Piggyback | 40662 | | | 70662 |
| Quick Connects | 16-14 Ga. | .110 Tab Female | 40194 | | | 70194 |
| | | .187 Tab Female | 40195 | | | 70195 |
| | | .187 Tab Male | 40198 | | | |
| | | .250 Tab Female | 40180 | 60180 | 80180 | 70180 |
| | | .250 Tab Male | 40181 | 60181 | 80181 | 70181 |
| | | .250 Piggyback | 40663 | | | 70663 |
| Quick Connects | 12-10 Ga. | .250 Tab Female | 40187 | 60187 | 80187 | 70187 |
| | | .250 Tab Male | 40186 | 60186 | 80186 | 70186 |
| | | .375 Tab Female | 40166 | | | 70166 |
| | | .250 Piggyback | 40664 | | | 70664 |
| Bullets | 22-18 Ga. | .157 Fem Bullet | 40285 | | | 70285 |
| | | .157 Male Bullet | 40284 | | | 70284 |
| | | .180 Fem Bullet | 40785 | | | 70785 |
| | | .180 Male Bullet | 40784 | | | 70784 |
| | | .157 Fem Bullet | 40185 | | | 70185 |
| Bullets | 16-14 Ga. | .157 Male Bullet | 40184 | | | 70184 |
| | | .180 Fem Bullet | 40685 | | | 70685 |
| | | .180 Male Bullet | 40684 | | | 70684 |
| | | .195 Fem Bullet | 40485 | | | 70485 |
| | | .195 Male Bullet | 40484 | | | 70484 |
| | | .195 Female Bullet | 40385 | | | 70385 |
| Fully Ins. Quick Connects | 22-18 Ga. | .250 Tab Female | 40207 | 60179 | 80179 | 70207 |
| | | .250 Tab Male | 40206 | | | 70206 |
| | 16-14 Ga. | .250 Tab Female | 40209 | 60183 | 80183 | 70209 |
| | | .250 Tab Male | 40208 | | | 70208 |
| | 12-10 Ga. | .250 Tab Female | 40213 | 60199 | 80199 | 70213 |
| | | .250 Tab Male | 40212 | | | 70212 |
| Oval Fully Ins. Quick Connects | 22-18 Ga. | .250 Tab Female | 44179 | | | 74179 |
| | | .250 Tab Male | 44178 | | | 74178 |
| | 16-14 Ga. | .250 Tab Female | 44183 | | | 74183 |
| | | .250 Tab Male | 44182 | | | 74182 |

Crimp & Seal (A) (D)



Crimp & Seal (A)

Solder & Seal (B)



Solder & Seal (B)

Crimp, Solder & Seal (C)



Crimp, Solder & Seal (C)

The terminals are copper (.110 alloy). The tubing is a high quality polyolefin or Nyax. Seamless connectors used on butts. Multiple wall heat shrinkable tubing, clearly marked. Rings and spades are brazed seam. Color coded with wire size.